



Load Testing, Inspection & Rigging  
608 Hangar Drive • New Iberia, LA 70560  
Phone (337) 365-1022 • Fax (337) 365-1024  
Toll Free (877) 246-3905

### NDT FIELD INSPECTION REPORT

Customer: NWS Job. #: \_\_\_\_\_  
 Ordered By: Jonathan Date: 19 July 11  
 RIG/OCS-G: \_\_\_\_\_ Specification:  BS EN 12079  
 P.O. #: \_\_\_\_\_  DNV 2.7-1  
 OTHER \_\_\_\_\_

#### Magnetic Particle (MT)

#### Dye Penetrant (PT)

Procedure Used \_\_\_\_\_ REV \_\_\_\_\_  
 Wet \_\_\_\_\_ Dry \_\_\_\_\_ Cont \_\_\_\_\_  
 AC \_\_\_\_\_ DC \_\_\_\_\_ Residual \_\_\_\_\_  
 Yoke# \_\_\_\_\_ Demagnetized  Yes  No  
 Coil# \_\_\_\_\_  
 UV Lamp Intensity \_\_\_\_\_ UW/CM2 W/L Intensity \_\_\_\_\_ fc  
 Bath Strength \_\_\_\_\_ % 100 ML Tube  
 White Contrast Batch # \_\_\_\_\_  
 Particle Batch # \_\_\_\_\_

Procedure Used \_\_\_\_\_ REV \_\_\_\_\_  
 W/L Intensity \_\_\_\_\_ FC \_\_\_\_\_  
 Developer BATCH# \_\_\_\_\_  
 Dye BATCH# \_\_\_\_\_

#### Visual Inspection (VT)

Procedure Used VT P-001 REV 02  
 W/L Intensity \_\_\_\_\_ FC \_\_\_\_\_

ITEM DESCRIPTION Bottle Rack SERIAL # NWS 1011

VT only

VT on entire visible structure

OK

Perry Batista

ASNT / TC — IA LEVEL II INSPECTOR