



Load Testing, Inspection & Rigging  
608 Hangar Drive • New Iberia, LA 70560  
Phone (337) 365-1022 • Fax (337) 365-1024  
Toll Free (877) 246-3905

N No 53618

### NDT FIELD INSPECTION REPORT

Customer: NWS Job #: \_\_\_\_\_

Ordered By: Jonathan Date: 19 July

RIG/OCS-G: \_\_\_\_\_ Specification:  BS EN 12079  
 DNV 2.7-1  
 OTHER \_\_\_\_\_

P.O. #: \_\_\_\_\_

#### Magnetic Particle (MT)

Procedure Used \_\_\_\_\_ REV \_\_\_\_\_

Wet \_\_\_\_\_ Dry \_\_\_\_\_ Cont \_\_\_\_\_

AC \_\_\_\_\_ DC \_\_\_\_\_ Residual \_\_\_\_\_

Yoke# \_\_\_\_\_ Demagnetized  Yes  No

Coil# \_\_\_\_\_

UV Lamp Intensity \_\_\_\_\_ UW/CM2 W/L Intensity \_\_\_\_\_ fc

Bath Strength \_\_\_\_\_ % 100 ML Tube

White Contrast Batch # \_\_\_\_\_

Particle Batch # \_\_\_\_\_

#### Dye Penetrant (PT)

Procedure Used \_\_\_\_\_ REV \_\_\_\_\_

W/L Intensity \_\_\_\_\_ FC

Developer BATCH# \_\_\_\_\_

Dye BATCH# \_\_\_\_\_

---

#### Visual Inspection (VT)

Procedure Used VT P-001 REV 02

W/L Intensity \_\_\_\_\_ FC

ITEM DESCRIPTION Bottle Rack SERIAL # NWS 1384

VT only

VT on entire visible structure

(D)

Perry Batista

ASNT / TC — IA LEVEL II INSPECTOR