



Load Testing, Inspection & Rigging
608 Hangar Drive • New Iberia, LA 70560
Phone (337) 365-1022 • Fax (337) 365-1024
Toll Free (877) 246-3905

N No 53614

NDT FIELD INSPECTION REPORT

Customer: NWS Job. #: _____

Ordered By: Jonathan Date: 19 July 11

RIG/OCS-G: _____ Specification: BS EN 12079
 DNV 2.7-1
 OTHER _____

P.O. #: _____

Magnetic Particle (MT)

Procedure Used _____ REV _____

Wet _____ Dry _____ Cont _____

AC _____ DC _____ Residual _____

Yoke# _____ Demagnetized Yes No

Coil# _____

UV Lamp Intensity _____ UW/CM2 W/L Intensity _____ fc

Bath Strength _____ % 100 ML Tube

White Contrast Batch # _____

Particle Batch # _____

Dye Penetrant (PT)

Procedure Used _____ REV _____

W/L Intensity _____ FC

Developer BATCH# _____

Dye BATCH# _____

Visual Inspection (VT)

Procedure Used VT P-001 REV 08

W/L Intensity _____ FC

ITEM DESCRIPTION Bottle Rack SERIAL # NWS 1956

VT only

VT on entire visible structure

(OK)

Perry Batista

ASNT / TC — IA LEVEL II INSPECTOR