



Load Testing, Inspection & Rigging  
608 Hangar Drive • New Iberia, LA 70560  
Phone (337) 365-1022 • Fax (337) 365-1024  
Toll Free (877) 246-3905

NDT FIELD INSPECTION REPORT

Customer: National Welding Supply Job #: 062811-  
Ordered By: Jessie Date: 28 Jun 11  
RIG/OCS-G: \_\_\_\_\_ Specification:  BS EN 12079  
 DNV 2.7-1  
P.O. #: \_\_\_\_\_  OTHER \_\_\_\_\_

Magnetic Particle (MT)

Dye Penetrant (PT)

Procedure Used \_\_\_\_\_ REV \_\_\_\_\_  
Wet \_\_\_\_\_ Dry \_\_\_\_\_ Cont \_\_\_\_\_  
AC \_\_\_\_\_ DC \_\_\_\_\_ Residual \_\_\_\_\_  
Yoke# \_\_\_\_\_ Demagnetized  Yes  No  
Coil# \_\_\_\_\_  
UV Lamp Intensity \_\_\_\_\_ UW/CM2 W/L Intensity \_\_\_\_\_ fc  
Bath Strength \_\_\_\_\_ % 100 ML Tube  
White Contrast Batch # \_\_\_\_\_  
Particle Batch # \_\_\_\_\_

Procedure Used \_\_\_\_\_ REV \_\_\_\_\_  
W/L Intensity \_\_\_\_\_ FC \_\_\_\_\_  
Developer BATCH# \_\_\_\_\_  
Dye BATCH# \_\_\_\_\_

Visual Inspection (VT)

Procedure Used VT-P-001 REV 02  
W/L Intensity 100 FC \_\_\_\_\_

ITEM DESCRIPTION Bottle Rack SERIAL # 2006

(VT)  
(0117)

vt) padare welds and load bearing welds  
and entire visible structure

Accepted

Tyler Beach