



Load Testing, Inspection & Rigging
608 Hangar Drive • New Iberia, LA 70560
Phone (337) 365-1022 • Fax (337) 365-1024
Toll Free (877) 246-3905

N No 53611

NDT FIELD INSPECTION REPORT

Customer: NWS Job. #: _____

Ordered By: Jonathon Date: 19 July 11

RIG/OCS-G: _____ Specification: BS EN 12079
 DNV 2.7-1
 OTHER _____

P.O. #: _____

Magnetic Particle (MT)

Dye Penetrant (PT)

Procedure Used _____ REV _____ Wet _____ Dry _____ Cont _____ AC _____ DC _____ Residual _____ Yoke# _____ Demagnetized <input type="checkbox"/> Yes <input type="checkbox"/> No Coil# _____ UV Lamp Intensity _____ UW/CM2 W/L Intensity _____ fc Bath Strength _____ % 100 ML Tube White Contrast Batch # _____ Particle Batch # _____	Procedure Used _____ REV _____ W/L Intensity _____ FC _____ Developer BATCH# _____ Dye BATCH# _____ <h4>Visual Inspection (VT)</h4> Procedure Used <u>VT P-001</u> REV <u>02</u> W/L Intensity _____ FC _____
--	--

ITEM DESCRIPTION Bottle Rack SERIAL # NWS 2009

VT only

VT on entire visible structure

(OK)

Perry Batista
 ASNT / TC — IA LEVEL II INSPECTOR