



Load Testing, Inspection & Rigging  
608 Hangar Drive • New Iberia, LA 70560  
Phone (337) 365-1022 • Fax (337) 365-1024  
Toll Free (877) 246-3905

N No 54010

### NDT FIELD INSPECTION REPORT

Customer: National Welding Supply Job. #: 062811-

Ordered By: Sesse Date: 28 Jun 11

RIG/OCS-G: \_\_\_\_\_ Specification:  BS EN 12079

DNV 2.7-1

OTHER \_\_\_\_\_

P.O. #: \_\_\_\_\_

#### Magnetic Particle (MT)

#### Dye Penetrant (PT)

Procedure Used \_\_\_\_\_ REV \_\_\_\_\_  
 Wet \_\_\_\_\_ Dry \_\_\_\_\_ Cont \_\_\_\_\_  
 AC \_\_\_\_\_ DC \_\_\_\_\_ Residual \_\_\_\_\_  
 Yoke# \_\_\_\_\_ Demagnetized  Yes  No  
 Coil# \_\_\_\_\_  
 UV Lamp Intensity \_\_\_\_\_ UW/CM2 W/L Intensity \_\_\_\_\_ fc  
 Bath Strength \_\_\_\_\_ % 100 ML Tube  
 White Contrast Batch # \_\_\_\_\_  
 Particle Batch # \_\_\_\_\_

Procedure Used 6 REV \_\_\_\_\_  
 W/L Intensity \_\_\_\_\_ FC \_\_\_\_\_  
 Developer BATCH# \_\_\_\_\_  
 Dye BATCH# \_\_\_\_\_

#### Visual Inspection (VT)

Procedure Used VT-P-001 REV 02  
 W/L Intensity 100 FC \_\_\_\_\_

ITEM DESCRIPTION Bottle Rack SERIAL # 2709

(VT ONLY)

vt) padwelds and load bearing welds and entire visible structure

Accepted

*Tyler Beal*

ASNT / TC — IA LEVEL INSPECTOR